STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/01/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	15.8	1.0	0.0	6	0	7.55
04:20	15.9	0.0	0.0	6	0	7.60
08:10	15.9	0.9	0.0	8	0	7.59
12:10	15.7	0.6	0.0	9	0	7.65
16:10	15.9	1.0	1.0	7	0	7.59
20:00	15.7	1.0	0.0	8	0	7.23

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/02/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	15.7	1.5	0.0	7	0	7.20
04:15	15.9	1.2	0.0	9	0	7.40
08:00	15.7	3.2	0.0	7	0	7.40
12:10	15.8	0.8	0.0	7	0	7.56
16:10	15.8	0.4	0.0	7	0	7.63
20:20	15.7	3.4	0.0	7	0	7.67

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/03/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	15.8	1.6	0.0	8	0	7.61
04:20	15.8	2.4	0.0	8	0	7.71
08:00	15.8	1.6	0.0	8	0	7.21
12:00	15.5	1.9	0.0	7	0	
16:00	15.6	-1.0	0.0	8	0	7.90
20:00	15.7	0.0	0.0	8	0	7.80

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/04/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	15.8	0.4	0.0	8	0	7.70
04:15	15.7	0.2	0.0	9	0	7.65
08:00	15.6	0.4	0.0	13	0	7.60
12:00	15.6	-1.0	0.0	7	0	7.76
16:00	15.6	-1.1	0.0	7	0	7.62
19:45	15.6	0.0	0.0	8	0	7.24

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/05/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	15.6	0.0	0.0	7	0	7.20
04:20	15.6	0.0	0.0	7	0	7.86
08:00	15.0	7.6	0.0	12	0	7.86
16:30	15.0	1.0	0.0	9	0	7.52
19:45	15.0	0.6	0.0	8	0	7.70

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/06/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	15.0	0.0	0.0	8	0	7.20
04:20	15.0	0.8	0.0	8	0	7.59
08:00	15.0	1.5	0.0	10	0	7.83
12:00	15.0	1.5	0.0	8	0	7.93
16:00	15.4	0.9	0.0	6	0	7.61
20:20	15.2	1.7	0.0	8	0	7.33

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/07/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	15.1	0.9	0.0	8	0	7.53
04:20	15.3	1.1	0.0	7	0	7.79
08:15	15.6	0.3	0.0	8	0	7.59
12:45	15.4	0.0	0.0	8	0	7.83
16:30	15.5	0.0	0.0	8	0	7.53
20:15	15.4	0.8	0.0	8	0	7.16

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	11/08/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	15.5	0.0	0.0	8	0	7.47
04:20	15.6	0.0	0.0	8	0	7.51
08:10	15.5	0.0	0.0	9	0	7.78
12:10	15.5	0.0	0.0	8	0	7.37
16:10	15.4	0.0	0.0	7	0	7.39
20:15	15.4	0.9	0.0	8	0	7.76