STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/01/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.2	0.0	0.0	17	0	7.30
04:20	10.1	0.0	0.0	14	1	7.88
08:15	11.3	0.0	0.6	15	0	7.37
12:15	10.5	0.0	0.5	17	0	8.71
16:15	11.3	0.0	0.6	13	0	9.34
20:00	11.0	0.0	0.5	14	0	9.00

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/02/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	11.1	0.0	0.0	15	0	8.50
04:00	11.3	0.0	0.0	15	0	7.24
08:25	8.8	0.2	0.0	15	1	7.68
12:30	10.4	0.0	0.0	19	1	9.57
16:30	13.0	0.0	0.0	15	1	7.53
20:20	14.1	0.0	0.0	16	0	7.62

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/03/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	14.0	0.0	0.0	16	1	7.99
04:20	13.9	0.0	0.0	15	0	8.02
08:15	9.2	0.0	0.0	16	0	7.35
12:15	10.8	0.0	0.0	22	0	10.24
16:15	10.8	0.0	0.0	12	0	7.46
20:20	10.7	0.0	0.0	15	1	7.41

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/04/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.9	0.6	0.0	14	1	7.59
04:20	10.8	0.5	0.0	14	1	7.49
08:15	8.8	0.4	0.0	15	0	7.66
12:15	11.5	0.9	0.0	17	0	7.11
16:15	11.7	0.6	0.0	16	0	7.15
20:20	12.0	0.0	0.0	16	1	7.97

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/05/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	12.0	0.0	0.0	15	1	7.95
04:20	9.7	0.0	0.0	16	0	7.57
08:15	10.9	0.0	0.0	13	0	9.52
12:15	11.2	0.0	0.0	14	0	7.67
16:15	11.0	0.0	0.0	13	0	7.37
19:10	11.2	0.0	0.0	14	0	7.40

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/06/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	11.2	0.4	0.3	16	1	7.86
04:20	11.0	0.0	0.0	15	1	7.71
08:10	11.1	0.5	0.0	15	1	7.67
12:10	5.9	0.0	0.0	14	1	7.81
16:10	10.7	0.0	0.0	21	1	7.31
20:20	10.8	0.0	0.0	16	0	7.87

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/07/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.9	0.0	0.0	15	0	7.90
04:20	10.7	0.0	0.0	15	1	7.91
08:30	11.4	0.0	0.0	14	1	7.48
12:30	11.1	0.0	0.0	13	0	7.58
16:30	10.5	0.0	0.0	15	1	7.62
20:10	10.4	0.0	0.0	14	1	7.16

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/08/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	10.8	0.0	0.0	15	0	7.20
04:00	11.5	0.0	0.0	16	0	7.48
08:15	11.2	0.0	0.0	13	0	7.76
12:15	10.8	0.0	0.0	15	0	7.10
16:15	9.2	0.0	0.0	14	0	7.34
20:10	10.2	0.0	0.0	15	0	7.40

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/09/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	10.0	0.0	0.0	16	0	7.40
04:00	9.6	0.0	0.0	17	0	7.44
08:25	8.6	0.0	0.0	15	0	7.74
12:30	9.2	0.0	0.0	16	0	7.65
16:25	9.6	0.0	0.0	17	0	7.62
19:20	12.4	0.0	0.0	14	0	7.77

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/10/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:10	12.0	0.0	0.0	15	0	7.60
04:00	12.5	0.0	0.0	14	0	7.40
08:15	12.3	0.0	0.0	15	0	7.52
12:20	11.3	0.0	0.0	13	0	7.64
16:00	11.7	0.0	0.0	14	0	8.11
20:00	11.8	1.0	0.0	18	0	7.81

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/11/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
04:20	12.2	1.1	0.0	15	1	7.90
08:05	12.3	0.0	0.0	15	0	7.35
12:15	12.1	0.0	0.0	15	0	7.34
16:20	12.2	0.7	0.0	13	0	7.47
20:20	11.7	1.3	0.0	14	0	7.80

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/12/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	11.1	2.3	0.0	14	1	7.89
04:20	10.9	3.0	0.0	16	0	7.77
08:10	12.0	1.1	0.0	14	0	7.47
12:15	11.2	0.9	0.0	13	0	7.56
15:50	11.3	0.8	0.0	15	0	7.42

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/13/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	11.0	2.1	0.0	15	1	7.87
04:20	10.9	2.4	0.0	15	1	7.89
08:10	11.1	0.0	0.0	15	1	7.34
12:10	14.5	0.4	0.0	14	1	7.63
16:10	12.8	0.0	0.0	12	1	7.65
20:20	11.5	1.3	0.0	14	1	7.81

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/14/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	11.4	2.4	0.0	15	1	7.99
04:40	11.5	0.9	0.0	14	1	7.89
13:05	11.2	0.0	0.0	15	1	8.05
20:00	11.5	0.0	0.0	14	1	8.00
23:30	11.0	0.0	0.0	14	1	7.90

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/15/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
04:05	12.0	0.0	0.0	15	1	7.70
08:15	11.6	0.0	0.0	13	1	7.90
12:15	10.9	0.0	0.0	13	0	7.55
16:15	11.3	0.0	0.0	16	1	7.31
20:00	11.7	0.0	0.0	15	1	7.50

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/16/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
04:05	11.7	0.0	0.0	14	1	7.42
08:15	11.9	0.5	0.0	13	0	7.38
12:15	10.9	0.0	0.0	12	1	7.37
16:15	11.1	1.0	0.0	15	1	7.09
20:20	11.1	1.3	0.0	16	1	8.91

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/17/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	11.0	4.2	0.0	14	1	8.40
04:20	11.1	2.3	0.0	11	1	8.27
08:15	10.5	0.0	0.0	17	0	8.80
12:15	10.9	0.4	0.0	12	0	7.37
16:15	10.9	0.3	0.0	12	0	7.25
20:20	10.8	0.0	0.0	14	1	7.26

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/18/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.9	3.8	0.0	14	1	7.71
04:20	11.0	2.7	0.0	15	1	7.78
08:15	10.4	0.0	0.0	12	1	7.54
12:15	11.1	0.0	0.4	17	0	7.16
16:15	10.4	0.0	0.5	13	0	7.57
19:45	10.5	0.1	0.0	15	1	7.41

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/19/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	10.6	0.0	0.0	15	1	7.50
04:15	10.7	1.5	0.0	15	0	7.58
08:15	10.8	2.8	0.0	14	0	7.58
12:15	11.4	0.5	0.0	26	0	7.21
16:15	11.1	3.9	0.0	15	0	7.39
19:15	11.2	0.6	0.0	15	1	7.58

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/20/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
04:15	11.0	0.4	0.0	16	1	8.96
08:10	11.0	3.4	0.0	13	1	8.79
12:10	11.1	1.4	0.0	12	1	8.18
20:15	10.5	0.4	0.0	15	1	7.51

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/21/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.6	2.3	0.0	15	1	7.86
04:20	10.5	2.0	0.0	15	1	7.57
08:15	11.0	0.3	0.0	14	0	7.28
12:15	11.7	0.4	0.0	14	0	7.58
16:15	11.6	0.3	0.0	13	0	7.26
20:10	11.4	0.5	0.0	15	1	7.28

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/22/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	11.6	0.5	0.0	14	1	7.30
04:00	11.3	2.8	0.0	17	1	7.25
08:10	10.8	0.4	0.0	15	0	7.42
12:30	11.1	2.4	0.0	16	0	7.82
16:20	11.6	0.0	0.0	16	0	9.56
20:00	11.5	0.0	0.0	15	0	9.20

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/23/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	11.5	1.0	0.0	15	0	8.50
04:05	11.4	1.4	0.0	15	1	8.55
08:15	11.4	0.0	0.0	16	0	10.28
12:15	10.8	0.0	0.0	14	0	7.67
16:15	11.0	0.0	0.5	12	0	7.53
20:20	10.8	1.0	0.0	13	1	7.78

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/24/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:15	10.9	3.8	0.0	14	1	7.81
04:20	10.8	3.0	0.0	13	1	7.66
08:15	10.7	2.4	0.0	13	0	7.89
12:15	11.0	3.3	0.0	14	0	7.52
16:15	10.9	2.6	0.0	13	0	7.62
20:00	10.5	3.8	0.0	15	1	7.65

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/25/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.8	1.5	0.0	15	1	7.58
04:15	10.9	3.9	0.0	15	1	7.60
07:55	10.8	2.3	0.0	14	0	7.82
11:45	11.1	2.9	0.0	13	0	8.04
16:15	10.9	4.3	0.0	15	0	7.67
20:15	11.0	1.3	0.0	15	1	7.78

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/26/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.9	3.3	0.0	15	1	7.88
04:10	10.9	3.5	0.0	14	1	7.78
08:10	10.2	1.8	0.0	13	0	7.92
12:15	10.9	2.3	0.0	15	0	7.67
16:10	10.9	2.5	0.0	14	0	7.64
20:20	10.8	0.8	0.0	15	1	7.85

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/27/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:20	10.9	1.1	0.0	15	1	7.76
04:20	10.8	1.2	0.0	14	1	7.70
08:10	10.9	2.4	0.0	15	1	7.93
12:10	10.8	2.3	0.0	14	1	7.85
16:10	10.7	1.9	0.0	13	1	7.71
19:45	10.5	1.8	0.0	14	1	7.57

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/28/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	10.4	1.7	0.0	14	1	7.55
04:10	10.4	1.8	0.0	14	1	7.49
08:10	10.8	4.7	0.0	16	0	7.91
12:15	11.0	2.2	0.0	13	0	8.02
16:15	10.9	2.6	0.0	12	0	7.78
20:10	11.0	2.4	0.0	13	0	7.80

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/29/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	10.9	2.4	0.0	15	1	7.44
04:00	10.5	2.5	0.0	19	1	7.28
08:15	10.6	2.5	0.0	18	1	7.22
12:15	10.5	2.4	0.0	14	1	7.05
16:15	10.7	2.4	0.0	17	0	7.29
20:00	10.5	2.4	0.0	16	0	7.35

STACK DISCHARGE MONITORING REPORT

facility name:	Fenimore Landfill	Emission Point	
address:	100 Mountain Road Ledgewood, NJ		Scrubber Stack Effluent
analyzer:	QRAe MultiRAE Lite	serial #:	PGM6208
		date:	09/30/15

time	O2 %	SO2 ppm	H2S ppm	CO ppm	VOC ppm	pH
00:05	10.8	2.5	0.0	17	0	7.30
05:00	11.2	3.0	0.0	19	0	7.40
08:15	11.7	2.5	0.0	14	0	8.90
12:15	10.9	2.1	0.0	19	0	7.50
16:15	11.4	3.0	0.0	14	0	7.67
20:20	11.0	2.8	0.0	12	1	7.55